Insured/Applicant Name:		Application	on / Policy #:		
Address Inspected: Lake Worth, FL 33467					
Actual Year Built: 2001	Date Inspected: 03/10/2025				
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
-					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps:150A Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150A Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present		☐ Double taps			
☐ Blowing fuses		☐ Exposed wiring			
☐ Tripping breakers		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size ☐ Scorching			
☐ Loose wiring ☐ Improper grounding		Other (explain)			
☐ Corrosion					
☐ Over fusing					
General condition of the electrical system: ✓ Satisfactory Unsatisfactory (explain)					
Supplemental information					
Panel age: 24 Yr(s) Year last updated: Original Year last updated: Year last updated: Year last updated	Second Panel Panel age:23 Yr(s) Year last updated: Original Brand/Model: Square D		Wiring Type ☑ Copper ☐ NM, BX or Conduit		

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection:N/A					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 3 Yr(s) Year last updated: 2022 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Garage					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher \(\times \) \(\to \) \(\to \) Refrigerator \(\times \) \(\to \) \(\to \) Washing machine \(\times \) \(\to \) \(\to \) Water heater \(\times \) \(\to \) \(\to \) Showers/Tubs \(\times \) \(\to \) \(\to \)	Satisfactory Unsatisfactory N/A Toilets X				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material:		Secondary Roof Covering material: Roof age (years):Yr(s) Remaining useful life (years): _Yr(s) Date of last roofing permit: Date of last update: If updated (check one):			
Overall condition: ☑ Satisfactory ☐ Unsatisfactory (explain below)		Overall condition: Satisfactory Unsatisfactory (explain below)			
Any visible signs of damage / deterior (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking Yes Interior ceilings Yes No	☑ No	Any visible signs of damage / deter (check all that apply and explain below Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or til Soft spots in decking Visible hail damage Any visible signs of leaks? Interior ceilings Yes No	v) es : ☑ No		
Additional Comments/Observations (use additional pages if needed):					
Re-Roof Permit # B-2023-01	1397				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Michael Strano Inspector Signature	CEO Title	HI9693 License Number	03/10/2025 Date		
			Dale		
Insight Home Inspections Company Name	Home Inspector License Type	561.252.5202 Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.






House Front

House View

Water heater



Water heater label 2017



TPR Valve







Copper & PVC plumbing










Roof Pics










B-2023-011397-0000 () Reroofing - SFD/Duplex - Complete

Further Desc: TILE TO TILE - 5/12 - P & S

03/16/2023 Application Date 03/20/2023 Issued Date













AC & HVAC Mfg Dates 2023 & 2022



